



**1** Engine compartment:  
Cowl: Treat via existing holes; (notice pollen filter right side - treat with caution) Treat console for engine suspension on right side, under headlamps, behind fusebox and under airfilter body. See fig 4 for treatment around spring strut. See fig 4 for treatment of top members in front wing. See fig 6 for treatment of longitudinal members.




**2** Bonnet lid:  
Front: Treat via existing and plugged holes. By windshield:  
Drill 3 holes: under rubber strip and existing hole by hinge. Treat panel flange all round.




**8** Front door:  
Treat via 3 drilled holes and existing drain hole rear.




**9** C-pillar:  
Treat via 3 drilled holes.  
B-pillar:  
Treat via 1 drilled hole under lock mounting and existing plugged hole (grommet).



**10** Rear door:  
3 drill holes for correct treatment. Uppermost drill hole for treatment of top member. See fig 11 for drilling at correct level.




**3** Spring strut:  
Treat via existing hole and around reinforcement plate.




**4** Member behind engine:  
Treat via existing holes.




**5** B-pillar:  
Treat via 2 drilled holes.




**6** Top members in front wing:  
Treat via existing hole.




**7** Longitudinal member front:  
Treat via existing holes.




**11** Rear door:  
Drill 1 hole above rubber strip to treat top member.




**14** Rear panel:  
Remove cover plate. Drill 1 hole right and 1 left.



**12** Doors in general:  
Treat around door hinges.



**13** Rear wing:  
Remove tail light. Treat via existing holes.

















**15** Tailgate:  
Treat via 3 existing plugged holes.



**16** Tailgate:  
3 drill holes for correct treatment.



Overview underside



CITROËN

- Area
- Drill and plug hole
- Drill hole
- Use of tools
- Existing hole

- Existing plugged hole
- Zoom in detail
- No treatment