

Treatment diagram

Daewoo Matiz Model 1999





Cowl


behind spring struts, under battery box and head lights. Drill 1 hole right side above fluid reservoir. Remainder via existing holes in radiator grille. Treat Locking plate/reinforcements:

Treat via existing holes and up under.










Treat via existing holes.



Floor level



Illustration nr. 6






Rear door: 1 drill hole behind rubber strip.


for drilling behind rubber strip.

Rear door: 3 drill holes for correct treatment. See fig 6A


B-pillar: 3 drill holes. Uppermost drill hole above lock mounting. 2nd and 3rd hole in panel curves.



































© Tektrol Mineralolier A/S, Denmark

Tailgate: Treat via 2 drilled holes as well as via existing plugged hole.


Zoom on detail

No treatment
















C-pillar: Treat via 1 drilled hole and existing plugged hole.





Area

Drill and plug hole

 \triangleright

Drill hole

Use of tools

0

Existing hole

Existing plugged hole

୭

DAEWOO




Treatment diagram

Daewoo Matiz Model 1999

Underside




13 **Overview underside** 14 **w** 15 16









plus reinforcement by longitudinal member forward.

DAEWOO

Area

Drill and plug hole

 \triangleright

Drill hole

Use of tools

0

Existing hole

Existing plugged hole

୭

Treat via existing holes. reinforcement by engine suspension:

Longitudinal member by rack bushing plus

Treat via existing holes.

Longitudinal members front:

eatment of top member. Existing hole by brake hose

arch front: Remove wheel arch liner for correct

Rear panel:

Treat via existing holes.

Treat via existing holes.

Vheel






over exhaust:

Treat via existing holes.

Cross member and area with reinforcements

Longitudinal members centre: Treat via existing holes.




wheel arch front: Cross member and reinforcement before Treat via existing holes.

3 drill holes for correct treatment


reinforcement on right. Reinforcements for rack plus minor


Treat via existing holes.

Cross member above rack-and-pinion:














radiator:

freat via existing holes.













© Tektrol Mineralolier A/S, Denmark

Zoom on detail No treatment