

Treatment diagram

Mercedes Vito Model 2004






Floor level



Engine compartment: Cowl: Treat via existing holes and from sides. Treat on top of longitudinal member and under battery box.




Bonnet lid: Treat via existing and plugged holes. By windscreen: Flip up lining. Treat via existing




B-pillar: Treatment via 2 existing plugs. Remove door switch / door stop. Treat via existing



Side door: 4 drill holes for correct treatment. Drill hole 5 cm. below door switch.



Side door: Fig. for correct treatment. (caution when advancing lance).




A-pillar: Treat via 3 drilled holes. See fig. 4.




A-pillar: Treat via 1 drilled hole under rubber strip.




Front door top member: Fig: drilling at correct level.




Area by sliding rail: Treat from each s ide.




Area by sliding rail: Treat from each side.



D-pillar/roof frame: Treat via existing holes.



Rear doors: Treatment via existing and plugged holes











Front door bottom:
Treat via existing holes in door bottom. Treat with lance. (caution when advancing lance).















Mercedes Vito

Model 2004







Cross member and auxiliary members above rear axle assembly:
Treat via existing and plugged holes. See fig 7.




Reinforcement for wheel suspension. Treat via existing aperture.



Reinforcement behind drive shaft: Treat via existing holes and gaps.




Cross and longitudinal member centre: Treat via existing and plugged holes.




Wheel arch rear: Treat behind wheel arch liner where pos-




Longitudinal member/reinforcement in wheel arch front:
Treat via existing holes.




Rear panel and reinforcement: Treat via existing and plugged holes.



Longitudinal, cross and auxilliary members: Treat via existing and plugged holes.




Reinforcement under radiator and front axle assembly:
Treat via existing holes.



Reinforcement behind drive shaft: Treat via existing holes.



Cross member above front axle assembly: Drill 1 hole for correct treatment.



A-pillar: Treat via existing plugged holes.



Wheel arch front top member: Treat via existing holes and gaps.















