



Chery Eastar 4D - Sedan

Model 2007




Floor level





Engine compartment:
Cowl: Remove 12 clips. Flip plastic plate - treat right across.
(notice pollen filter right side - treat with caution)
Treat behind spring struts, along top of longitudinal members, under airfilter and battery box, around hinges for bonnet lid cross member obove radiator.
See fig. 3, 4 and 5.



Bonnet lid: Treat via 1 drilled hole, 1 existing plugged hole and via existing holes.



Front door: Treat via 4 drilled holes and 1 drain hole. Uppermost drill hole for inside reinforcement.



B-pillar: No treatment because of safety belt and airbag censor



15

Rear door: Treatment via 4 drilled holes.
Uppermost drill hole for inside reinforcement.



Engine compartement - sectional view: Fig: correct treatment of cowl.



Treatment diagram

Engine compartement - sectional view: Treatment of reinforcement in front of radiator.



A-pillar: Treat via 2 drilled holes.



C-pillar: Treat via 3 drilled holes. No spraying towards cabin. Remainder via treatment from rear wing.



Removal of tail light from boot: Remove 4 nuts and pulling back.

Tailgate: Treat via 5 drilled holes as well as via existing holes.



Rear wing: Treat via 2 drilled holes. No spraying towards cabin.



Engine compartement - sectional view: Fig. for correct treatment of reinforcements on spring struts both sides.

CHERY























Chery Eastar 4D - Sedan

Model 2007

Underside





Treatment diagram



Wheel arch rear/longitudinal member: Treatment via 1 drill hole and existing holes. Panel: See fig 2. Wheel arch rear/panel and C-pillar: Treat via existing plugged holes. Note that panel may in places be filled with foam.




Panels: Treatment via 7 plugged holes and 7 drill holes in inner panel. Drill via existing plugged holes.



Wheel arch front/longitudinal members: Treat via 2 drilled holes as well as via Wheel arch front/panel: Treat via existing plugged hole and 1 drill holes. Drill via existing plugged hole. existing holes.
Panel og top member: See fig. 5 and 6.




Wheel arch front top member: Treat via existing holes.




Treat area between rear panel and bumper. Side section: Treat via existing plugged holes.



Rear axle assembly: Treat via existing holes and gaps.



Cross member above rear axle assembly: Treat via existing holes.



Cross member before tank: Treat via 4 drill holes and existing holes.




Longitudinal members centre: Treat via existing and plugged holes.
Small cross member centre: See fig 12.



Small cross member centre: Treat via 2 drilled holes as well as via existing hole.



Cross member above front axle assembly: Treat via existing holes.



Front axle assembly/supports: Treat via existing holes and gaps.



Cross member under radiator: Treat via existing holes.



Member for bumper and reinforcements: Treat via existing holes and gaps.



Longitudinal member before wheel arch rear: Treat via existing hole. Reinforcement via 1 drilled hole.



Small cross member after front wheel arch: Treat via existing hole.

















Illustration nr. 2

Illustration nr. 5

Mustration nr. 6