

Treatment diagram

Floor level




Engine compartment:


Cowl: Treat via 1 hole in plastic plate above brake fluid reservoir plus via existing holes and from sides. Fig 4.

Cross member behind engine: Treat via existing holes. Treat on top of longitudinal member and under battery box.


Fig. 3: Treat top member in wing and gap between front wing and wheel arch liner.








Treat via 1 hole in plastic plate above brake fluid reservoir.




Bonnet lid: Treat via existing holes in front. Remainder via existing plugged holes.




Treatment via 4 drilled holes. See fig 7 for correct drilling.



Front door bottom: Treat via 1 hole abt. 5 cm upwards.





Rear wing from boot: Treat via existing lug. See fig 12. for correct treatment.



Drill 2 holes for correct treatment.



Rear wing: Treat via existing hole with lance and area around tail light.



A-pillar:

Area

Drill 2 holes for correct treatment.



Drill and plug hole

Use of tools

Existing hole

Existing plugged hole Zoom on detail

No treatment



Rear panel side: Treat via 1 drilled hole. Caution when advancing lance under tail light.






Treat via grommet with flex hose.



Treatment diagram


Fiat Stilo 2D - HB Model 2002

Overview underside






Wheel arch rear: Remove wheel arch liner, mount new type (plastic or aluminium).




Drill 1 hole for treatment of B-pillar and panel.





Area

Panel: Treat via all existing plugged holes.



Wheel arch front: Flip out wheel arch liner. Treat with lance.





Rear panel: Treat via existing holes, and behind wheel arch liner where possible.






Fig: drilling.

Longitudinal members centre and 2 * reinforcement: Longitudinal members: Treat via existing plugged holes. Reinforcements: See fig 10 and 11.






Reinforcement by front axle assembly: 3 drill holes for correct treatment.

Reinforcement before wheel box forward. Treat via 1 drilled hole and existing hole.



Longitudinal members rear: Treat via existing plugged holes.



Treat via existing plugged hole.



Drill hole

Use of tools


Zoom on detail Existing plugged hole

No treatment




Treat via gap between bumper and panel.

Cross member before tank: Treat via 1 drilled hole and existing plugged holes. See fig 8 for drilling at correct level.







Front axle assembly: Treat via existing holes.

Longitudinal member front and reinforcement for bumper: Treat via existing holes and gaps.

© Tektrol Mineralolier A/S, Denmark