Floor level



Engine compartment

Cowl: Treat via 1 hole in plastic plate above brake fluid reservoir plus via existing holes and from Cross member behind engine: Treat via existing holes. Treat on top of longitudinal member and sides. Fig. 4:

under battery box.


Fig. 3: Treat top member in wing and gap between front wing and wheel arch liner








front wing and wheel arch liner. I reat top member in wing and gap between



A-pillar: Drill 2 holes for correct treatment.



B-pillar:

Treat via 1 drilled hole and existing plugged

Treat via 2 drilled holes. Drill hole 3 cm below existing plug for locking cylinder. Drill close to door plate. See also fig 8. Front door top:





plate fold and close to door plate. See also fig Treat via 2 drilled holes. Uppermost drill hole: Rear door top: is drilled under lock mounting. Drill level with Drill in plate flange under existing plug. Hole





Remove plastic plate. Treat via existing holes. Rear panel:



Flip up lining. Treat via existing hole.

Rear wing/rear panel:



Tailgate side by bumper



Treat via 1 hole abt. 5 cm upwards Front door bottom:



C-pillar: Treat via 2 drilled holes.



Treat via existing lug. Double plating around tail light and reinforcement via existing holes. Rear wing from boot:











fluid reservoir.

Treat via 1 hole in plastic plate above brake







 \triangleright


Drill hole














Wheel arch rear: (plastic or aluminium). Remove wheel arch liner. Mount new type



Treat via existing plugged hole. C-pillar/panel:



Flip out wheel arch liner. Treat with lance. Wheel arch front




arch liner where possible. Treat via existing holes, and behind wheel Wheel arch front:



Rear panel:



Treat via gap between bumper and panel



See fig 8 for drilling at correct level. Treat via 1 drilled hole and all plugged holes. Cross member before tank:


Illustration nr. 8

Illustration nr. 10



Fig: drilling. Cross member before tank:










Illustration nr.



3 drill holes for correct treatment. Reinforcement by front axle assembly:



Reinforcement before wheel box forward. Treat via 1 drilled hole and existing hole.



Treat via existing hole and 1 plugged hole. Longitudinal member after wheel arch rear:









Treat via existing plugged holes











 \bigcirc

Existinghole



Treat via existing plugged holes

Longitudinal member rear:







