



Treatment diagram

Peugeot 1007 **Model 2005** 


Floor level





Treat via existing holes and gaps.






Sliding door rear: Treat via existing plugged hole.



Engine compartement - sectional view: Fig. for correct treatment.





Engine compartement - sectional view: Fig. for correct treatment.






B-pillar and rear wing: Drill 2 holes for correct treatment. Panel: See fig 10.





Rear wing: Remove tail light. Treat via 1 drilled hole. Treat via existing hole. Treat via existing plugged hole.





PEUGEOT



Drill and plug hole

Drill hole

Existing hole

Existing plugged hole

Zoom on detail







<u>jernbetjente skydedøre</u>

Panel: Fig. for correct treatment.






Treatment diagram


Peugeot 1007

**Model 2005** 

Underside

## **General view of underside**







Wheel arch rear/longitudinal member: Treat via 3 drilled holes. 3 reinforcements. Treat via existing holes.



Wheel arch front/longitudinal member/ reinforcement: Treat via existing holes and gaps.



Wheel arch rear/panel: Treat via 2 drilled holes as well as via exist-ing plugged hole.





Area



Illustration nr. 7


Wheel arch front: See fig. 4 and 5 for correct treatment. See fig. 6 and 7 for correct treatment.


Illustration nr. 4

Illustration nr. 5


Illustration nr. 6

Wheel arch front reinforcement: Treat via existing holes and gaps.






Small cross member and longitudinal member centre: Treat via existing holes.



Longitudinal members centre/reinforcement: Treat via existing holes. See fig 12. Fig 13.



Drill hole


Use of tools

Existing hole

Zoom on detail Existing plugged hole







Cross member above rear axle assembly: Treat via existing holes.

Longitudinal-/auxilliary members rear: Treat via 1 drilled hole each side.