

Treatment diagram

Bonnet lid.


flange.

Treat front via existing holes.

By windscreen. Remove 5 clips.

Side. Remove 1 clip centre and along plate


Floor level



## Engine Compartment

Cowl. Treat from bonnet lid hinges and flip out plastic plate and inject in under it. Treat engine suspension and reinforcement in right hand side, under battery and air filter body on the right. Locking plate and u-member for bumper, treat via existing holes. See fig 3 for correct treatment of front wing.









tion nr 4A 


> Front door. Treat via 3 drilled holes. See fig 4A for drilling at correct level.



A-pillar. Drill at top close to rubber strip and via existing plugged hole behind grommet.








C-pillar. Treat via 2 drilled holes, top drilling is for part treatment of rear wing. See fig 7A for drilling at correct level.


C-pillar Drill 1 hole directly below rubber strip for part treatment of rear wing.



C-pillar and rear wing from cabin. Treatment via existing holes behind lining. Rear wing. Treat behind lining.



Rear panel and reinforcement. Drill 1 hole right and 1 hole left between rubber strip and tail light.



Tailgate at roof. 1 drilling and via grommet.





Drill hole

Drill and plug hole

Use of tools

Existing hole



No treatment



Rear door. 3 holes for correct treatment.





Rear panel. Drill 1 hole by lock for correct treatment.

Tailgate. side and bottom. Drill 2 holes and existing plugged hole for correct treatment.



Treatment diagram

Skoda Fabia **Model 2000** 

Underside





Illustration nr. 3




Wheel arch rear. Treatment via 2 existing holes by shock absorber and behind arch liner where possible.



Panel and longitudinal member rear. Treatment via existing plugged holes.





Treatment of outer, centre and inner panel via existing holes.

Drill and plug hole

Area





Use of tools

Illustration nr. 4

Small cross member by panel. Treat via existing plugged holes.


Drill hole







1 hole in reinforcement for wheel suspension 1 hole in liner by mounting screw.


Rear panel and u-member for bumper. Treat via clearing by rear panel and bumper.





Longitudinal member after tank. Treatment via 2 drilled holes ...








Forstærkning for forbro. 1 boring højre og 1 boring i venstre side. Se illustration nr. 13 for boring i korrekt niveau.

Illustrating the drilling at correct level.



Longitudinal members rear. Treat via existing holes.Observe existing hole behind cover plate to the left.



Longitudinal member by wheel suspension rear. Drill 1 hole for correct treatment.











Zoom on detail









Longitudinal member before tank. 3 holes for correct treatment.



Longitudinal members centre and exhaust plate.Longitudinal members. Treat via existing and plugged hole and behind exhaust plate where possible.



Axle beam. Treat via existing holes.



Longitudinal member forward. Treat via existing hole with flexhose.