



Treatment diagram

VW Passat 4D - Sedan

Model 2005


Floor level






Engine compartment: Cowl: Flip plastic plate right side - treatment in under, left side treatment via existing holes. Treatment behind spring struts, on top of longitudinal members, under battery and air filter box and treatment of locking plate via existing holes.

Bonnet lid: Treat via existing holes. Treatment via exist-ing plugged holes for washer.











Treat via 2 drilled holes.



Cross member behind engine: Treat via existing holes.




Reinforcement and engine suspension: Treat via existing holes and gaps.




A-pillar: Treat via 2 drilled holes as well as via existing plugged hole.




Front door: No treatment pressure sensor for AIRBAG.






Rear wing from boot: Flip lining - treat in all directions.



Tailgate side: Drill 2 holes for correct treatment.




Area

Drill and plug hole

Drill hole







Rear door: Treat via 3 drilled holes. Centre drill hole level with screws for locking device. Lower drilling level with side C2229

Rear panel: Remove plastic plate and treat via existing holes.

Tailgate by rear window: Treat via 2 drilled holes. **Note the shallow drilling depth**.





Treatment diagram

VW Passat 4D - Sedan


Model 2005

Underside





Treatment via 5 plugged holes. Longitudinal members centre: Treat via existing holes.



Wheel arch rear: Treat via existing and plugged holes.


VOLKSWAGEN



Drill and plug hole


Wheel arch rear/panel: Treatment via 2 plugged holes.

Area



Wheel arch front: Longitudinal member: Drill 2 holes for cor-rect treatment. See fig 6 and 7.






Wheel arch front top member: Treat via existing holes and gaps.



Cross member above rear axle assembly: Treat via existing holes.

Cross member under tank: Treat via 1 drilled hole. See fig 11.



Small cross member after front wheel arch: Treat via existing holes. Longitudinal member before wheel arch rear: Treat via existing plugged holes.



Use of tools

Existing hole

Zoom on detail





Rear panel: Treat via gap between bumper and panel.






Fig: drilling at correct level.





Longitudinal member rear: Treat via existing hole.





Longitudinal member front: Treat via exist-ing hole.