Area









Floor level

Fiat Brava 4D HB Model 1995

Treatment diagram

12, 13 12, 14 15, 16, 17

1 hole at top, 2 holes + existing hole in frame, 2 holes at bottom of tailboard.

Drill 1 hole each side.

Rear panel

Right across wing via 2 holes by C-pillar and 2 drill holes by taillight.

Rear wing Tailgate

C-pillar

Drill 2 holes. Treat via existing hole from wheel arch.

Instructions

Component

Abbreviations: long. m. = longitudinal member, (L) = left, (R) = right

Drilling

| Component | Instructions | Drillings | Fig |
|------------------------|---|-----------|-------|
| Cowl | Remove cover plate. Treat via existing hole. | | - |
| Engine compartement | Engine Top members: drill in the left member, existing hole in right member. Bonnet lid: Flip up lining. compartement Treat via existing holes. | - | 2, 3 |
| Front wings | Front part via hole from engine compartement. Rear part via drilling in liners - do not drill in the right | 2 | 4, 5 |
| A-pillar | Drill 2 holes. Remove door switch. | 2 | 9 |
| Front doors | 5 holes (the 2 top ones owing to members), the rest to treat door plate. | 5 | 7, 8 |
| Rear doors | 5 holes (the 2 top ones owing to members), the rest to treat door plate. | 5 | 9, 10 |
| B-pillar | 1 drill hole to treat B-pillar. | - | 1 |
| | Abbreviations: long. m. = longitudinal member, (L) = left, (R) = right | | |






































No treatment

Drillings Instructions Drill 2 holes in member in right side. Drill 1 hole left side. Drilling in plastic plug. Treat via existing holes. Drill in line with line with panel casing in each side. Drill in centre of member by cable for Longitudinal Employer 1 Cross member 1

Component

Abbreviations: long. m. = longitudinal member, (L) = left, (R) = right





Underside

| gs | Fig. | Component | Instructions | Drillings | Fig. |
|----|------------|----------------------------|---|-----------|---------|
| | 19, 20 | Panel boxes | Treat via existing plugged holes. Inner panel: 3 drill holes each side. | 3 | 24, 25, |
| | 21, 22, 23 | Cavity behind front axle | Treat via 2 holes each side. | 2 | 27, 28 |
| | | Cross member front | Drill 1 hole right side. | - | 29 |
| | | Longitudinal members front | 2 drill holes in each side from front wheel arch. | 2 | 30 |
| | | | Abbreviations: long. m. = longitudinal member, (L) = left, (R) = right | | |











•





















Zoom on detail